

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 07/30/2015  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>155153</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING <b>01, 02, 03</b>  B. WING _____		(X3) DATE SURVEY COMPLETED  <b>R</b> <b>07/27/2015</b>
NAME OF PROVIDER OR SUPPLIER  <b>HEALTHWIN</b>			STREET ADDRESS, CITY, STATE, ZIP CODE <b>20531 DARDEN RD</b> <b>SOUTH BEND, IN 46637</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
{K 000}	<p>INITIAL COMMENTS</p> <p>A Post Survey Revisit (PSR) to the Life Safety Code Recertification and State Licensure Survey conducted on 06/22/15 and 06/23/15 was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a).</p> <p>Survey Date: 07/27/15</p> <p>Facility Number: 000073 Provider Number: 155153 AIM Number: 10028820</p> <p>At this PSR survey, Healthwin was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC) and 410 IAC 16.2. The original building was surveyed with Chapter 19, Existing Health Care Occupancies.</p> <p>This two story facility with a basement was determined to be of Type II (222) construction and was fully sprinklered with the exception of the areas cited at K56. The facility has a fire alarm system with smoke detection on all levels including in the corridors, in areas open to the corridors and in 9 of 122 resident rooms. Battery operated smoke detectors were in 113 of 122 resident sleeping rooms. The facility has a capacity of 143 with a census of 131 at the time of this survey.</p> <p>All areas where the residents have customary access were sprinklered with the exception of the areas cited at K56. All areas providing facility services were sprinklered with the exception of</p>	{K 000}			

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 07/30/2015  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>155153</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING <b>01, 02, 03</b>  B. WING _____		(X3) DATE SURVEY COMPLETED  <b>R</b> <b>07/27/2015</b>
NAME OF PROVIDER OR SUPPLIER  <b>HEALTHWIN</b>			STREET ADDRESS, CITY, STATE, ZIP CODE <b>20531 DARDEN RD</b> <b>SOUTH BEND, IN 46637</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
{K 000}	Continued From page 1	{K 000}			
{K 000}	INITIAL COMMENTS  A Post Survey Revisit (PSR) to the Life Safety Code Recertification and State Licensure Survey conducted on 06/22/15 and 06/23/15 was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a).  Survey Date: 07/27/15  Facility Number: 000073 Provider Number: 155153 AIM Number: 100288820  At this Life Safety Code survey, Healthwin was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC) and 410 IAC 16.2. The 2012 addition was surveyed with Chapter 18, New Health Care Occupancies.  This two story facility with a basement was determined to be of Type II (222) construction and was fully sprinklered with the exception of the areas cited at K56. The facility has a fire alarm system with smoke detection on all levels including in the corridors, in areas open to the corridors and in 9 of 122 resident rooms. Battery operated smoke detectors were in 113 of 122 resident sleeping rooms. The facility has a capacity of 143 with a census of 131 at the time of this survey.  All areas where the residents have customary	{K 000}			

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 07/30/2015  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>155153</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING <b>01, 02, 03</b>  B. WING _____		(X3) DATE SURVEY COMPLETED  <b>R</b> <b>07/27/2015</b>
NAME OF PROVIDER OR SUPPLIER  <b>HEALTHWIN</b>			STREET ADDRESS, CITY, STATE, ZIP CODE <b>20531 DARDEN RD</b> <b>SOUTH BEND, IN 46637</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
{K 000}	<p>Continued From page 2</p> <p>access were sprinklered with the exception of the areas cited at K56. All areas providing facility services were sprinklered with the exception of the areas cited at K56.</p> <p>A Post Survey Revisit (PSR) to the Life Safety Code Recertification and State Licensure Survey conducted on 06/22/15 and 06/23/15 was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a).</p> <p>Survey Date: 07/27/15</p> <p>Facility Number: 000073 Provider Number: 155153 AIM Number: 100288820</p> <p>At this Life Safety Code survey, Healthwin was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC) and 410 IAC 16.2. The 2012 addition was surveyed with Chapter 18, New Health Care Occupancies.</p> <p>This two story facility with a basement was determined to be of Type II (222) construction and was fully sprinklered with the exception of the areas cited at K56. The facility has a fire alarm system with smoke detection on all levels including in the corridors, in areas open to the corridors and in 9 of 122 resident rooms. Battery operated smoke detectors were in 113 of 122 resident sleeping rooms. The facility has a capacity of 143 with a census of 131 at the time of this survey.</p> <p>All areas where the residents have customary</p>	{K 000}			

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 07/30/2015  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>155153</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING <b>01, 02, 03</b>  B. WING _____		(X3) DATE SURVEY COMPLETED  <b>R</b> <b>07/27/2015</b>
NAME OF PROVIDER OR SUPPLIER  <b>HEALTHWIN</b>			STREET ADDRESS, CITY, STATE, ZIP CODE <b>20531 DARDEN RD</b> <b>SOUTH BEND, IN 46637</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
{K 000}	Continued From page 3 access were sprinklered with the exception of the areas cited at K56. All areas providing facility services were sprinklered with the exception of the areas cited at K56.	{K 000}			